

**SJRA Segment W1A - Existing Fault Protection System | Egypt Fault**

Station/Description	Initial Survey March, 2015 Elev.	September, 2015 Elev.	March, 2016 Elev.	September, 2016 Elev.	April, 2017 Elev.	September, 2017 Elev.	March, 2018 Elev.	September, 2018 Elev.	March, 2019 Elev.	September, 2019 Elev.	March, 2020 Elev.
Sta 103+72 Top Square Nut on 2" Steel Cap	187.20	187.20	187.20	187.20	187.20	187.20					
Sta 103+82 Top 2" Steel Pipe (NO CAP)	186.93	186.93	186.93	186.93	186.93	186.93					
Sta 108+70 Top Square Nut on 2" Steel Cap	190.28	190.27	190.27	190.27	190.27	190.26					
Sta 108+80 Top 2" Steel Cap	190.31	190.30	190.31	190.30	190.30	190.30					

**TBM "W1A":**

Top of South Bolt on Signal Light Pole at the southeast corner of Research Forest Drive and FM 2978

Elevation = 195.68' (SJRA Project Vertical Control Datum)

**Notes:**

1. All elevations are referenced to the SJRA Groundwater Reduction Plan Project Vertical Control Datum. Project Benchmark: SJRA Benchmark No. 5, Elevation = 212.00 feet.